

GENERAL TERMS AND CONDITIONS

28. NOMINATIONS

Northern will support the following standard nomination cycles (all times are CCT pursuant to NAESEB WGQ Standard No. 0.3.17):

o The Timely Nomination Cycle  
On the day prior to gas flow:

- 1:00 p.m. Nominations leave control of the Service Requester (SR);
- 1:15 p.m. Nominations are received by Northern (including from Title Transfer Tracking Service Providers (TTTSPs));
- 1:30 p.m. Northern sends the Quick Response to the SR;
- 4:30 p.m. Northern receives completed confirmations from Confirming Parties;
- 5:00 p.m. SR and Point Operator receive scheduled quantities from Northern.

Scheduled quantities resulting from Timely Nominations should be effective at the start of the next Gas Day.

o The Evening Nomination Cycle  
On the day prior to gas flow:

- 6:00 p.m. Nominations leave control of the SR;
- 6:15 p.m. Nominations are received by Northern (including from TTTSPs);
- 6:30 p.m. Northern sends the Quick Response to the SR;
- 8:30 p.m. Northern receives completed confirmations from Confirming Parties;
- 9:00 p.m. Northern provides scheduled quantities to the affected SR and Point Operator, including bumped parties (notice to bumped parties).

Scheduled quantities resulting from Evening Nominations should be effective at the start of the next Gas Day.

o The Intraday 1 Nomination Cycle  
On the current Gas Day:

- 10:00 a.m. Nominations leave control of the SR;
- 10:15 a.m. Nominations are received by Northern (including from TTTSPs);
- 10:30 a.m. Northern sends the Quick Response to the SR;
- 12:30 p.m. Northern receives completed confirmations from Confirming Parties;
- 01:00 p.m. Northern provides scheduled quantities to the affected SR and Point Operator, including bumped parties (notice to bumped parties).

Scheduled quantities resulting from Intraday 1 Nominations should be effective at 2:00 p.m. on the current Gas Day.

o The Intraday 2 Nomination Cycle  
On the current Gas Day:

- 2:30 p.m. Nominations leave control of the SR;
- 2:45 p.m. Nominations are received by the Northern (including from TTTSPs);
- 3:00 p.m. Northern sends the Quick Response to the SR;
- 5:00 p.m. Northern receives completed confirmations from Confirming Parties;
- 5:30 p.m. Northern provides scheduled quantities to the affected SR and Point Operator, including bumped parties (notice to bumped parties).

Scheduled quantities resulting from Intraday 2 Nominations should be effective at 6:00 p.m. on the current Gas Day.

o The Intraday 3 Nomination Cycle  
On the current Gas Day:

- 07:00 p.m. Nominations leave control of the SR;
- 07:15 p.m. Nominations are received by the Northern (including from TTTSPs);
- 07:30 p.m. Northern sends the Quick Response to the SR;
- 09:30 p.m. Northern receives completed confirmations from Confirming Parties;
- 10:00 p.m. Northern provides scheduled quantities to the affected SR and Point Operator.

Scheduled quantities resulting from Intraday 3 Nominations should be effective at 10:00 p.m. on the current Gas Day. Bumping is not allowed during the Intraday 3 Nomination Cycle.